

	Sanchar Nigam Executives' Association, Kerala SNEA Bhavan, Dharmalayam Road, Trivandrum - 695001		
	Circle President George Varghese DE Tripunithura, ENK 9447162900 (M) gvsnea@gmail.com	Circle Secretary T.Santhosh Kumar SDE Vizhinjam, TVM 9446072525 (M) cssneakerala@gmail.com	Circle Treasurer G.Premkumar SDE Karyavattom, TVM 9447102277 (M) premkumarg92@gmail.com

No. SNEA/KRL/CGM/2015-16/ 53 Dated 20-7-2016

To

Chief General Manager Telecom,
BSNL, Kerala Circle,
Thiruvananthapuram.

Respected Sir,

Sub:- Maintenance of cable records and DCRMS.
Ref:- DO. No. Op/Gen/MIS/2016-17 14th July 2016

As per the letter under reference it has been instructed to input the data regarding faulty cable pairs and route diagram up to DPs in the DCRMS. The purpose of maintaining the cable record for the maintenance as well as for making use of the available UG cable is of no doubt. But we are sorry to bring to the attention to CGMT that DCRMS implemented in the circle has not resulted any purpose rather than wasting huge man power and other resources for the **Dream Project** of the previous circle administration. We don't want to go in to the details, our humble request is to find out number of login to the system after it was declared as "go live" in March 2015 for its utility. We are of the view that the effectiveness of a product/tool/process can be best judged by seeing its consumption, demand or utility. Sir, it appears that the inputs from IT cell (most of them never became part of the external plant) may be getting the more significance rather than the suggestions of the field units even in external plant maintenance.

For the upgradation of cable system, we are of the view that most of our pillar, DP and MDF need rehabilitation for which we require sufficient man power and material. Since these points are visible we may ensure the rehabilitation of MDF, Pillar and DP and DATA correction as the first step for the improvement of cable system. Secondly major cable faults are to be attended which is possible only by a special drive. It may appear that these things are the routine work of the external plant maintenance and does not require any special direction/ effort at SSA/ Circle management level. It may be born in mind that all other assets other than external plant assets like switches, Transmission systems, power plant, Battery, EA, Computers, ACs etc are planned at SSA/ Circle/ Corporate level for AMC or for replacement in a time bound manner as life expired, change of Technology or irreparable. We are reporting these facts to the management after experiencing the genuine difficulties for the above routine works with the available

staff and material. It is requested to chalk out a plan at Circle/ SSA level for the rehabilitation of MDF, Pillar, DPs and for attending faults in major cables and for DATA correction in the existing CDR system by taking the inputs from field executives, field staff and contract labours at the earliest.

Thanking you,

Yours Sincerely



(T.Santhosh Kumar)
Circle Secretary,SNEA,
Kerala Circle.

Copy to :- GM IT/ GM(NWO-CFA)